

**D.Y.Patil College of Engineering & Polytechnic
Talsande, Kolhapur.**

Visit Report

on

Building Components

Date: - 12 -11-2021

Our civil engineering department had arranged an Industrial Visit for SYCE class. The venue was **University building under construction in college campus , Talsande**. Within visit students were came across the following points.

- 1) Details of building components.
- 2) Difference between substructure and super structures
- 3) Different levels in building
- 4) Different materials used
- 5) Staircase components.
- 6) Building margins

For this visit total 18 students were present along with 1 faculty members of the department.

HOD

Department of civil Engg



Foundation work



Difference of levels



Formwork





Staircase