

**D.Y.Patil Technical Campus (Polytechnic Wing)
Talsande, Kolhapur.**

Visit Report

On

Identification of Defects in Roads: Chavare Village Road

Date: 16/10/2023

Our civil engineering department had arranged an Industrial Visit for SYCE class under the course of **Highway Engineering (22301)**. The venue was **Chavare Village Road, Kolhapur** Within visit students were came across the following points.

- 1) Type of Road
- 2) Main Component Parts of Road
- 3) Identification of defects
- 4) Measure all dimensions

For this visit total 11 students were present along with 1 faculty members of the department.

HOD

Department of civil Engg



Bituminous Road



Carriage Way Width Measurement



Shoulder Width Measurement



Defected Edge of Road



Pot Hole Dimension Measurement



Pot Hole Depth Measurement



Cracks





All Students & Staff at Visit Location